


Konfigurasi PIN Modem CSI-21P Dengan Meter 3 Fasa Milik PLN


8 PIN & 4 PIN

(PIN MODEM CSI-21P. PIN 1 (P) = POWER**, PIN 4 (R) = RX, PIN 5 (T) = TX, PIN 6 (G)= GROUND)


EDMI/HEXING



ITRON



WASION



PIN	M*	KWH /RTU	PIN
1	PWR	PWR	1
4	RX	GND	4
5	TX	RX	5
6	GND	TX	6

PIN	M*	KWH /RTU	PIN
1	PWR	PWR	1
4	RX	RX	4
5	TX	TX	5
6	GND	GND	6

PIN	M*	KWH /RTU	PIN
1	PWR	PWR	1
4	RX	RX	4
5	TX	TX	5
6	GND	GND	7

*Socket bertanda M dihubungkan ke Modem

**Pin 1 optional. Bila menggunakan adaptor/PSU bisa diputus pinnya atau bila meter tidak ada powernya (Misalkan: Merk Hexing)